

COPYRIGHT:

All rights reserved. The information contained in Au rights reserved. The intrometor contained in this document is Copyright and cannot be reproduced or copied by any means without the written permission of Taylors Development Strategists Unit Trust. Any licence, express or implied, to use this document for any purpose whatsoever is restricted to the terms of agreen between Taylors Development Strategists Unit Trust and the instructing party. Any third party intending to use this information for any purpose shatsoever must first contact Taylors Development Sitrategists Unit Trust for written emission and suitability of application.

AMENDMENTS:

REV:	DATE:	DESCRIPTION:
1	30.03.23	BC DRAFT ISSUE 75%
2	13.04.23	BC DRAFT ISSUE
A	27.04.23	BC ISSUE

NOTES:

FLOOR PLAN LEGEND:

(FXX) Finish - Refer to Product and Materials Schedule Wall type - Refer to

> drawing A-810 Window number - Refer to drawing A-801

Door number - Refer to drawing A-801

SMOKE DETECTOR

PRELIMINARY NOT FOR CONSTRUCTION

PROJECT:

Project Name 11 DANUBE ST., VAUXHALL, DUNEDIN 9013

CLIENT:

LACHLAN CAMERON

DRAWING:

GROUND FLOOR PLAN

DRAWN	Author	CHECKED:	Checker
SCALE:	As indicate	ed @ A3	

REVISION:

A-202





Phone: +64.3.343.0802 | www.haylors-ds.co.rac Granicolds | N28W 8420041275139

		PROPERTY DETAILS	
Property	Key	5031344	
Print Date	e	10/09/2024 02:54 PM	
Address		11 Danube Street Dunedin	
Property	Туре	Situation	-
Property	Name		
Legal Des	scription	LOT 6 DP 10147	
	BU	ILDING PERMITS/CONSE	NTS
	Pre-1992	Historical Records (No CCC	Required)
	BIEV RESULTS		
	В	uilding Permit	
		Date !!-	
	AAB1	Details 9640927 10905 - Erect Dwelling (S	mith)
Number	Туре	Status	Started
H-1964-61890 (AAB19640927)	Building Permit	Historical Record	25/03/1964
		Details	
`	AAB19710	B07 4843 - Carport and Sundeck (!	McEachran)
Number	Туре	Status	Started
H-1971-73370 (AAB19710807)	Building Permit	Historical Record	28/10/1971
		Details	
	AAB19820992 279	94 - Additions to Dwelling - Extend L	iving Area (Baird)
Number	Туре	Status	Started
H-1982-91803 (AAB19820992)	Building Permit	Historical Record	15/04/1982
		Details	
	AAB19831076 4950	- Install Heater - Warmaire Inbuilt	Spaceheater (Baird)
Number	Туре	Status	Started
H-1983-93685 (AAB19831076)	Building Permit	Historical Record	02/06/1983

(AAB19831076)



	Drainage	Permit	
		Details	
AAD19	611251 G4672 - Drainage -	Lay Council Foul and Stormwat	ter Sewers, (McLaughlan)
Number	Туре	Status	Started
H-1961-183181 (AAD19611251)	Drainage Permit	Historical Record	17/07/1961
		Details	
	AAD19642506 G	8806 - Drainage New Dwelling ((Smith)
Number	Туре	Status	Started
H-1964-187550 (AAD19642506)	Drainage Permit	Historical Record	27/07/1964
		Details	
	AAD19642507 G8	3899 - Plumbing New Dwelling ((Smith)
Number	Туре	Status	Started
H-1964-187551 (AAD19642507)	Drainage Permit	Historical Record	01/08/1964
		Details	
	AAD19831244 K5376 -	Extend Stormwater Drainage, N	lo Plan (Baird)
Number	Туре	Status	Started
H-1983-216825 (AAD19831244)	Drainage Permit	Historical Record	18/05/1983
		Details	-
AAI	D19881773 L2556 - Repair a	nd Replace Sections of Sewer I	Orain, No Plan (Soper)
Number	Туре	Status	Started
H-1988-225455 (AAD19881773)	Drainage Permit	Historical Record	28/03/1988
		Details	
	AAD19891857 L4252 - F	Renew Sewer Drain to Boundar	y Trap (Soper)
Number	Туре	Status	Started
H-1989-227600 (AAD19891857)	Drainage Permit	Historical Record	08/03/1989
		Details	
	AAD19902047 L7644 -	Replace Cold Water Service, No	o Plan (Soper)

H-1990-229959 (AAD19902047)

Drainage Permit

Historical Record

11/09/1990

Building Consent

Details

Remove Walls/Replace with Beams between Kitchen/Dining/Living, Remove Fire, Install Escea DL850 Gas Fire in Lounge, Extend Partial Wall to meet Existing Wall in Bathroom, Reconfigure Bathroom Layout, Remove Shower/Replace with Shower over Bath

Number		Status	Started	
ABA-2021-240		Consent Lapsed	16/02/2021	
PIM	ВС	ICC	ССС	
	09/03/2021			

Details

Amendment to ABA-2021-240 - Revise Changes to Layout of Kitchen, Dining and Living Areas, Install Wet-Area Shower in Bathroom, Change Gas Fire From Escea DL850 to Escea DL960

Number		Status	Started	
ABA-2022-877		Consent Lapsed	12/05/2022	
PIM	BC	ICC	ССС	
	26/05/2022			

Details

Alter Dwelling - Remedial Work to Subfloor Structure, Insulation, Linings, Doors, Windows, Decking and Reclad Part Walls

Number		Status	Started	
ABA-2023-756		CCC Issued	15/05/2023	
PIM	ВС	ICC	CCC	
=======================================	05/09/2023		26/06/2024	

Details

Install Wagner Sparky CA Heater in Dwelling

Number		Status	Started	
ABA-2024-901		CCC Requested	19/06/2024	
PIM	ВС	ICC	ссс	
	26/06/2024			



		Details	
	Alter D	welling - Kitchen and Bathroor	m
Number		Status	Started
ABA-1995-333593 (ABA955084)		CCC Issued	06/11/1995
PIM	ВС	ICC	ССС
21/11/1995	21/11/1995		20/02/1996
		Details	
	ABA97045.	2 0452 - Add to Dwelling (Corr	nelius)
Number		Status	Started
ABA-1997-338985 (ABA970452)		CCC Issued	27/02/1997
PIM	ВС	ICC	ccc
06/03/1997	06/03/1997		29/08/1997
		Details	
	Drainage Altera	tions - New Stormwater Drain	to Existing
Number		Status	Started
ABA-1997-340789 (ABA972441)		CCC Issued	18/07/1997
PIM	ВС	ICC	ссс
21/07/1997	21/07/1997		25/07/1997
		Details	
	Add De	eck and Sliding Door to Dwellin	ng
Number		Status	Started
ABA-1998-342680 (ABA980511)		CCC Issued	02/03/1998
PIM	ВС	ICC	ссс
13/03/1998	13/03/1998		20/04/1998
		Details	
		Add to Ensuite	
Number		Status	Started
ABA-2004-304707 (ABA41941)		CCC Issued	30/06/2004
PIM	ВС	ICC	ССС
02/07/2004	02/07/2004		01/12/2004



BUILDING ACT - OTHER

Certificate of Acceptance

	Details	
Alter Bathroom to Enlarge Shower, Remove Bath, Install Vanity and Tiles		
Number	Status	Started
COA-2024-42	COA Issued	01/05/2024

PROPERTY ANALYSIS

NOTE: The Property Analysis section is additional information recorded in the computer system for your property. Full details of items can be obtained by requesting a Land Information Memorandum or Land Information Report from the Council Information Management Unit.

DISCLAIMER

The information in this report is provided in accordance with Sections 216 and 217 of the Building Act 2004.

No person should rely on this information without seeking appropriate, independent and professional advice.

Every care has been taken to ensure that the information supplied is accurate however Council does not give any guarantees, undertakings or warranties concerning the accuracy, completeness or up-to-date nature of the information provided and disclaims all liability whatsoever for any error, inaccuracy, irrelevance or incompleteness of the information.

The information provided does not constitute a Land Information Memorandum (LIM).

DEFINITION OF "STATUS" OF BUILDING CONSENTS

CCC REFUSED/ARCHIVED CONSENTS: In accordance with section 93(2)(b) of the Building Act, the consent was reviewed for code compliance after two years. Compliance with the Building Code could not be established and therefore the Code Compliance Certificate has been refused.

LAPSED CONSENTS: Section 52 of the Building Act 2004 requires that a building consent shall lapse and be of no further effect if work has not commenced within 12 months after the date of issue, or any further period allowed by the Building Consent Authority.

The application will be given a status of LAPSED if no extension of time to this period is applied for. This means that a new consent will be required if the work were to take place in the future.

NOTE: This is NOT a comprehensive list of all building consent statuses.



DEFINITION OF "ABBREVIATIONS"

Pim = Project Information Memorandum BC = Building Consent

ICC = Interim Code Compliance Certificate

CCC = Code Compliance Certificate

CER = Certifier

COA = Certificate of Acceptance

NTF = Notice to Fix

AMD = Amendment to a Building Consent

For Sale

11 Danube Street, Vauxhall



LAWRENCE PEETERS

DUNEDIN REAL ESTATE EXPERT

For Sale

11 Danube Street, Vauxhall



Scan to view property

LAWRENCE PEETERS

DUNEDIN REAL ESTATE EXPERT

021 992 993 lawrence.peeters@oatps.nz lawrencepeeters.co.nz





property awards 2023

DIGITAL MARKETING EXCELLENCE

Top performing salesperson Q1 2024

Otago